

Multi

P 081923Z
 FM NPIC WASHDC
 TO RUCSBR/SAC OFFUTT AFB OMAHA NEB
 RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAA/2D RTS BARKSDALE AFB LA
 RUEAHQ/DIA WASHDC
 RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
 RUEPIA/CIA WASHDC
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 2875

HFS

CJS

OTC

BTS

LCL

Grace (File)

OUT54043

1964 SEP 8 20 31Z

SEP 1964

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI).

1. CAMERA B-15 WAS USED IN MISSION 3942 FLOWN ON 4 SEPTEMBER 1964; PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: A PLUS DENSITY STREAK IS PRESENT 3.3" FROM THE INBOARD EDGE OF THE FILM THROUGHOUT THE MISSION. MINOR INBOARD ROLLER CHATTER OCCURS IN THE BEGINNING OF THE MISSION AND GRADUALLY DECREASES INTENSITY, ENDING IN PART 10. EMULSION LIFTS EXIST IN FRAME 1435 AND 1461. LARGE CHEMICAL STAINS ARE PRESENT IN FRAMES 1713 AND 1717 THROUGH 1720. HEAT SPLICES WITH ASSOCIATED HANDLING MARKS ARE IN FRAME 990 AND BETWEEN FRAMES 1065-1066. MANUFACTURING SPLICES OCCUR IN FRAMES 461 AND 1726 WITH ASSOCIATED DENDRITIC STATIC ON FRAMES 463 AND 1725 THROUGH 1728 RESPECTIVELY.

C. 9L SIDE: INBOARD ROLLER CHATTER IS PRESENT IN THE

-2-

FIRST 80 PERCENT OF THE MISSION. BLISTERS ARE NOTED IN FRAMES 494, 541, 803 AND 1049. EMULSION DIGS ARE NOTED IN FRAMES 495, 729 AND 734. NUMEROUS PINHOLES AND BLISTERS ARE NOTED BETWEEN FRAMES 1162 AND 1180. FRAME 608 AND 609 CONTAIN A PROFUSION OF EMULSION DEFECTS WHICH APPEAR TO HAVE BEEN CAUSED BY A FUNGUS GROWTH. THE DEFECTS ARE SMALL AND CIRCULAR IN APPEARANCE. THEY ARE IMAGED ON FRAME 608 AND LESS DISTINGUISHABLE ON FRAME 609. THIS IS A WANDERING PLUS DENSITY LINE APPROXIMATELY 0.5" FROM THE INBOARD EDGE IN FRAMES 885-888 WHICH CHANGES TO A SERIES OF SMALL DOTS ON FRAMES 889-894. A MINUS DENSITY COMET IS NOTED IN FRAME 470. THERE IS A HEAT SPLICE IN FRAME 955.

D. BOTH SIDES: EDGE STATIC IS PRESENT ALONG BOTH EDGES THROUGHOUT THE ENTIRE MISSION. THE TITLED FRAMES ARE NUMBERED FROM 0001 TO 1925.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES IN THIS MISSION.

3. POSITIVE.

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING ARE GOOD.

C. CLOUDS OBSCURE 45 PERCENT OF THE MISSION.

S E C R E T

-END OF MESSAGE-